

Note: Only accessible wells/piezometers within 150 feet of cross-section baseline are shown.

Sitewide Cross-Section C - C'
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

FIGURE **F-25**

DRAWN	JOB NUMBER	CHECKED	CHECKED DATE	APPROVED	APPROVED DATE
PCB	4088097619	NAM	1/2011	WJF	1/2011

4088097619 DWG 40.0
20110113 1:46