


## LEGEND

- Burial Trench
- Landfill Boundaries
- Facility and Zone 1 Boundary
- Perimeter Source Control Trench (PSCT)
- Plume Capture Collection Trench (PCT)
- Clay Barrier
- Creek
- Pond Outline
- RGPZ-15B — Lower HSU Piezometer
- RP-63C — Lower HSU Monitoring Well
- MET — Meteorological Station
- Gauged Measurement of DNAPL through March 2010
- Dissolved Concentrations of DNAPL Constituents greater than 1% of aqueous solubility
- Dissolved Concentrations of DNAPL Constituents greater than 10% of aqueous solubility
- Former Pond and Pad Subarea
- Historical Natural Drainage
- —?— Presence of DNAPL inferred by DNAPL at Landfill/Lower HSU contact

Plotted: 01-10-2011 3:36 PM By: pdcouvela
File: P:\4088097619\Casmalia_RI_Report\FIGS\f-4088097619f035.dwg

| NO. | DATE | REVISIONS | BY | CHK |
|---|---|---|---|---|
| | | | | |

| | | | |
|---|---|---|---|
| DRAWN: PCB | PROJECT NO: 4088097619 | | |
| ENGINEER: | SCALE: 1"= 400' | | |
| CHECKED: NAM | APPROVED: WJF | | |
| DATE: 1/2011 | DATE: 1/2011 | | |

**Final Remedial Investigation Report**

Casmalia Resources Superfund Site
Casmalia, California

**DNAPL in Lower HSU Observed or Inferred from Groudwater Concentrations Fall 2004 and Spring 2005 RI Sampling**

FIGURE F-35
SHEET: 1 OF 1
REVISION NUMBER: 0
DATE: January 2011